

I hereby certify that this correspondence is being deposited with the United States Postal Service as first class mail in an envelope addressed to: Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

Alexandria, VA 22313-1450.

Kathu 4100 Kathi Howard 10-6-00

## IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Serial No.:

10/733,564

Filed:

December 11, 2003

Patent No.:

6,937,482

Issued:

August 30, 2005

Applicant(s):

Robert W. Kooker, Paul E. White, and Thomas A. Bachman, II

Title:

COMPACT, HIGH EFFICIENCY, HIGH ISOLATION POWER AMPLIFIER

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

**Certificate** 

007 1 2 2006

ATTN:

DECISION AND CERTIFICATE OF CORRECTION

BRANCH OF THE PATENT ISSUE DIVISION

-----

## REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT FOR PTO MISTAKE (37 CFR §1.322 (a)) AND APPLICANT'S MISTAKE (37 C.F.R. §1.323)

Sir:

Attached in duplicate form, is Form PTO-1050, with at least one copy being suitable for printing. Many of the errors below are (or may be contended to be) the mistake of Applicant who states that the errors are of a minor nature or character and occurred in good faith, and correction thereof does not involve such changes in the patent as would constitute new matter or would require reexamination. At least one of the errors, which appear in the Form PTO-1050 was a typographical error which occurred through the fault of the U.S. Patent and Trademark Office ("PTO").

The exact column and line number where the errors are shown in the patent are as follows:

Column 3, line 65, reads "... subcircuits is described herein, though it is understood by a..." and should read -... subcircuits are described herein, though it is understood by a ... -.

Column 7, line 49, reads "...accordance with one aspect of the invention, connections..." and should read - ... accordance with one aspect of the invention, connection ... - .

Column 15, line 35 reads "...the feedforward power amplifier 10, as discussed" and should read – ...the feedforward power amplifier 10, as discussed. –.

Column 18, line 29 reads "...ments and obvious variations thereof is contemplated as..." and should read - ... ments and obvious variations thereof are contemplated as ... -.

Column 20, CLAIM 9, line 19 reads "...the lid structure having generally solid side wails extend-..." and should read – ...the lid structure having generally solid side walls extend-... –.

Please send the certificate to:

Kurt A. Summe, Esq. Wood, Herron & Evans, L.L.P. 2700 Carew Tower Cincinnati, Ohio 45202

As some of the errors are, or could be contended to be Applicant's mistakes, enclosed is a check for \$100.00 to cover the correction fee. If there is any further charge or credit due, please use Deposit Account No. 23-3000.

Respectfully submitted,

WOOD, HERRON & EVANS, L.L.P.

By:

Surt A. Summe, Reg. No. 36,023

WOOD, HERRON & EVANS, L.L.P. 2700 Carew Tower 441 Vine Street Cincinnati, Ohio 45202 (513) 241-2324

Printer's Trim Line

## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,937,482

DATED : August 30, 2005

INVENTOR(S): Kooker, et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 3, line 65, reads "... subcircuits is described herein, though it is understood by a..." and should read -... subcircuits are described herein, though it is understood by a ... -.

Column 7, line 49, reads "...accordance with one aspect of the invention, connections..." and should read - ... accordance with one aspect of the invention, connection ... -.

Column 15, line 35 reads "...the feedforward power amplifier 10, as discussed" and should read – ...the feedforward power amplifier 10, as discussed. –.

Column 18, line 29 reads "...ments and obvious variations thereof is contemplated as..." and should read — ... ments and obvious variations thereof are contemplated as ... —.


Column 20, CLAIM 9, line 19 reads "...the lid structure having generally solid side wails extend-..." and should read – ...the lid structure having generally solid side walls extend-... –.

MAILING ADDRESS OF SENDER:

Wood, Herron & Evans, L.L.P. 2700 Carew Tower 441 Vine Street Cincinnati, OH 45202-2917 PATENT NO. 6,937,482 No. of add'l copies

@ 50¢ per page: \_\_\_\_\_

PAGE 1 of 1 - -



Printer's Trim Line

## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,937,482

DATED : August 30, 2005

INVENTOR(S): Kooker, et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 3, line 65, reads "... subcircuits is described herein, though it is understood by a..." and should read -... subcircuits are described herein, though it is understood by a ... -.

Column 7, line 49, reads "...accordance with one aspect of the invention, connections..." and should read - ... accordance with one aspect of the invention, connection ... - .

Column 15, line 35 reads "...the feedforward power amplifier 10, as discussed" and should read – ...the feedforward power amplifier 10, as discussed. –.

Column 18, line 29 reads "...ments and obvious variations thereof is contemplated as..." and should read – ... ments and obvious variations thereof are contemplated as ... –.

Column 20, CLAIM 9, line 19 reads "...the lid structure having generally solid side wails extend-..." and should read – ...the lid structure having generally solid side walls extend-... –.

MAILING ADDRESS OF SENDER:

PATENT NO. 6,937,482

No. of add'l copies

@ 50¢ per page: \_\_

Wood, Herron & Evans, L.L.P. 2700 Carew Tower 441 Vine Street Cincinnati, OH 45202-2917

PAGE 1 of 1

